

Figure 1





Figure 3

ORIENTATION OF THE PHOTOMETER IN THE VERTICAL PLANE



Note: 1. Measurements Nos. 1, 3, 4, 6, 7, 9, 10, 12, 13, 15, 16 and 18 must be taken at a distance of 1 to 2 meters from the edge of the slope. Measurements Nos. 2, 5, 8, 11, 14 and 17 must be taken in the centre of the slope.

2. The segment of the slope may begin at any point determined by the inspector.

Figure 2

HEIGHT AND ANGLE OF THE PHOTOMETER ABOVE THE HORIZONTAL PLANE





FIGURE 4

MEASUREMENT GRID AND TARGETS FOR MEASURING POINTS



- A: Target for measuring points in row 1.
- B: Target for measuring points in row 2.
- C: Target for measuring points in row 3.
- D: Target for measuring points in row 4.
- E: Target for measuring points in row 5.
- F: Target for measuring points in row 6.