

$$CF_{CO_2} = \frac{\sum_{j=1}^n (CF_{PR,j} \times FE'_{CF,j})}{1000}$$